

# Career Progression - Drilling Floor

Offshore Installation  
Manager (OIM)

Toolpusher

Driller

Assistant Driller

Derrickman

Assistant Derrickman

Pumpman/  
Solids Control Technician

Roughneck/Floorhand

Roustabout

Maintenance Roustabout

Painter

*Assistant Driller and Driller can also move to the Safety Officer position*  
*Minimum 2 years experience as Assistant Driller before eligible for promotion to Driller*

*Assistant Crane Operator – minimum of two years experience required before eligible for promotion to Crane Operator*

*Basic Qualifications:  
Roughneck training course (2 -3 weeks); BST;  
HST; Current Medical; Experience on land rigs.*

*Preferred entry level qualification is becoming the  
2 or 3 year technology diploma*

*Promotion – in-house training and years of  
experience*

Crane Operator

Assistant Crane  
Operator

Chef / Chief Steward

Cooks

Steward

*Entry level :  
Catering staff often move to the deck – They are  
familiar with the rig and are used to working  
offshore*

*Painter – works from April to October*

Helideck Operator

